

## MAXNET II® - MP3FA - F Optics Active Chassis FIRMWARE UPDATE NOTICE



### Version:

- ▶ mn2f.1.6.37

### Issued:

- ▶ June 18, 2014

### Fixes:

- ▶ Selecting “save changes” on the CHASSIS tab doesn’t affect the relay state.
- ▶ SNMP heCommonLog Table correctly increments now.
- ▶ Log timing stamp going out of sequence.
- ▶ UTC time server field in configuration not adding time offset.
- ▶ Amplifier modules correctly display temperature thresholds HI=60,HIHI=70.
- ▶ Corruption of MAC/persistent memory when power cycling.
- ▶ Telnet soft-reboot command corrupting persistent settings.
- ▶ Persistent memory corrupting when upgrading firmware.
- ▶ SNMP traps not being generated.
- ▶ MPRFA/B modules correctly show dBmV instead of dBm on GUI.

### Known Issues:

- ▶ MPRFA/B - using front pushbutton to change default control state doesn’t store in persistent memory. Need to change control state using GUI or SNMP sets.
- ▶ MPRX-8F - OptRx alarms generated on GUI log display “input B”, should be “OptRx Input Status” or “OptRx Input Power”.
- ▶ Latest versions of Internet Explorer® will not display graphics correctly. It is a display issue only. No function loss.

## Service & Support

### Contact ATX Networks

Please contact ATX Technical Support for assistance with any ATX products. Please contact ATX Customer Service to obtain a valid RMA number for any ATX products that require service and are in or out-of-warranty before returning a failed module to the factory.

#### RF & OPTICAL TECHNICAL SUPPORT

Tel: (905) 428-6068

Toll Free: (800) 565-7488 (USA & Canada only)

► Press \*3 for **Technical Support**

► Then press 2 for **RF & Optical Products (MAXNET, SignalOn, HFC Enhance, PCI Filters, Q-Series, FLEXNET, SCN,**

**SMAC FiberLinx)**

Email: [rfsupport@atxnetworks.com](mailto:rfsupport@atxnetworks.com)

#### CUSTOMER SERVICE

ATX Networks

1-501 Clements Road West

Ajax, ON L1S 7H4 Canada

Tel: (905) 428-6068

Toll Free: (800) 565-7488 (USA & Canada only)

► Press \*1 for **Customer Service**

Fax: (905) 427-1964

Toll Free Fax: (866) 427-1964 (USA & Canada only)

Web: [www.atxnetworks.com](http://www.atxnetworks.com)

Email: [support@atxnetworks.com](mailto:support@atxnetworks.com)

Although every effort has been taken to ensure the accuracy of this document it may be necessary, without notice, to make amendments or correct omissions. Specifications subject to change without notice.

SignalOn® Series, MAXNET®, HFC Enhance®, PCI Filters®, Q-Series® & FiberLinx® are registered trademarks of ATX in the United States and/or other countries. SMAC<sup>SM</sup> is a service mark of ATX in the United States and/or other countries. Products or features contained herein may be covered by one or more U.S. or foreign patents. Other non-ATX product and company names in this manual are the property of their respective companies.



1-501 Clements Road West, Ajax, ON L1S 7H4 Canada

Tel +1 (905) 428-6068 Toll Free +1 (800) 565-7488

Fax +1 (905) 427-1964 Toll Free Fax +1 (866) 427-1964

[www.atxnetworks.com](http://www.atxnetworks.com) [support@atxnetworks.com](mailto:support@atxnetworks.com)