

## SOFTWARE RELEASE NOTE 4.2

### Software Revision:

- ▶ 4.2

### Issued:

- ▶ August 14, 2015

### Highlights of Changes

### New Features/Improvements:

- ▶ GUI: Added "Module Temperature" and "Module Temperature Alarm".

### Product Additions/Obsolescence:

- ▶ ChromaFlex: Added CCT1.

### Bug Fixes:

- ▶ Fixed SNMP notification format.
- ▶ Fixed typos in help menu.
- ▶ System software release note.
- ▶ Updated MIB files.

## Service & Support

### Contact ATX Networks

Please contact ATX Technical Support for assistance with any ATX products.

#### OPTICAL TRANSPORT TECHNICAL SUPPORT

Tel: (408) 227-3400

▶ Press 4 for **Technical Support for Optical Transport Products (ChromaFlex, I-HUB, Chromadigm, TranScend)**

Email: [opticalsupport@atxnetworks.com](mailto:opticalsupport@atxnetworks.com)

#### CUSTOMER SERVICE

InnoTrans Communications Inc.

(a Division of ATX Networks)

5850 Hellyer Avenue

San Jose, CA 95138 USA

Tel: (408) 227-3400

▶ Press 4 for **Customer Service**

Fax: (408) 227-3403

Web: [www.atxnetworks.com](http://www.atxnetworks.com)

Email: [opticalsales@atxnetworks.com](mailto:opticalsales@atxnetworks.com)

Changes affect all product lines unless otherwise noted (CD Chromadigm, TSD TranScend, CF ChromaFlex, I-HUB).

GUI: Graphical User Interface over HTTP, CLI: Local interface with handheld client.

See [firmware upgrade instructions](#).

Although every effort has been taken to ensure the accuracy of this document it may be necessary, without notice, to make amendments or correct omissions. Specifications subject to change without notice.



5850 Hellyer Avenue, San Jose, CA 95138 USA  
Tel +1 (408) 227-3400 Fax +1 (408) 227-3403  
[www.atxnetworks.com](http://www.atxnetworks.com) [opticalsupport@atxnetworks.com](mailto:opticalsupport@atxnetworks.com)