

UCrypt® IP to QAM Firmware:

Version:

- ▶ 1.5.2

Issued:

- ▶ June 2, 2011

System FW v1.5.2 includes:

- ▶ Output QAM module FW v2.20

Changelog:

- ▶ Improve filtering of non-configured channels at IP input port.

Service & Support

Please contact ATX Technical Support for assistance with any ATX products. Please contact ATX Customer Service to obtain a valid RMA number for any ATX products that require service and are in or out-of-warranty before returning a failed module to the factory.

DIGITAL VIDEO SUPPORT LINE

Tel: (905) 428-6068

Toll Free: (800) 565-7488 (USA & Canada only)

▶ Press *3 for **Technical Support**

▶ Then press 1 for **Digital Video Products**

E-mail: digitalvideosupport@atxnetworks.com

CUSTOMER SERVICE

ATX Networks

1-501 Clements Road West

Ajax, ON L1S 7H4 Canada

Tel: (905) 428-6068

Toll Free: (800) 565-7488 (USA & Canada only)

▶ Press *1 for **Customer Service**

Fax: (905) 427-1964

Toll Free Fax: (866) 427-1964 (USA & Canada only)

Web: www.atxnetworks.com

E-mail: support@atxnetworks.com

Although every effort has been taken to ensure the accuracy of this document it may be necessary, without notice, to make amendments or correct omissions. Specifications subject to change without notice.

1-501 Clements Road West, Ajax, ON L1S 7H4 Canada
Tel +1 (905) 428-6068 Toll Free +1 (800) 565-7488 Fax +1 (905) 427-1964 Toll Free Fax +1 (866) 427-1964
www.atxnetworks.com support@atxnetworks.com