

SOFTWARE RELEASE NOTE 4.4

Software Revision:

- ▶ 4.4

Issued:

- ▶ February 5, 2016

Highlights of Changes

New Features/Improvements:

- ▶ GUI: Added display of login user name.
- ▶ GUI/CLI: Added wavelength display.

Product Additions/Obsolescence:

- ▶ ChromaFlex: Added DMTx (1310), DMTx4 (ITU), Fixed Output CCT1-FO.

Bug Fixes:

- ▶ I-HUB attribute reading might be incorrectly retrieved from proxy parent module if the child module contains the identical attribute.
- ▶ Updated MIB files.

Service & Support

Contact ATX Networks

Please contact ATX Technical Support for assistance with any ATX products.

OPTICAL TRANSPORT TECHNICAL SUPPORT

Tel: (408) 227-3400

▶ Press 4 for **Technical Support for Optical Transport Products (ChromaFlex, I-HUB, Chromadigm, TranScend)**

Email: opticalsupport@atxnetworks.com

CUSTOMER SERVICE

InnoTrans Communications Inc.

(a Division of ATX Networks)

5850 Hellyer Avenue

San Jose, CA 95138 USA

Tel: (408) 227-3400

▶ Press 4 for **Customer Service**

Fax: (408) 227-3403

Web: www.atxnetworks.com

Email: opticalsales@atxnetworks.com

Changes affect all product lines unless otherwise noted (CD Chromadigm, TSD TranScend, CF ChromaFlex, I-HUB).

GUI: Graphical User Interface over HTTP, CLI: Local interface with handheld client.

See [firmware upgrade instructions](#).

Although every effort has been taken to ensure the accuracy of this document it may be necessary, without notice, to make amendments or correct omissions. Specifications subject to change without notice.



5850 Hellyer Avenue, San Jose, CA 95138 USA
Tel +1 (408) 227-3400 Fax +1 (408) 227-3403
www.atxnetworks.com opticalsupport@atxnetworks.com